

Topic: Using Epson Advanced Printer Driver APDTM301 with Ethernet IV Connect-it Module

Issue: Not able to print after installing APDTM301 drivers with default installation parameters

Scope: All released versions of Ethernet IV module

Date: June 08, 2005

Explanation:

Running Epson APDTM301 installation program ATM\_301E.exe prompts the user to “Select Install Module” to select printer models. It also prompts the user for “Printer Port Setting, etc” to set up the printer port. Completing this standard configuration installs the appropriate printer drivers and ethernet ports (ie. ESDPRT001). This standard configuration is not compatible with the Ethernet IV Module.

Solution:

Complete standard installation.

Using Windows Start->Settings->Printers:

For each installed Epson printer.

1. Select the printer Properties:
2. Add and select a Standard TCP/IP port with the appropriate IP address of your Epson printer (custom, raw, 9100)
3. Clear box for “Enable bidirectional support” (disable)